Series 007, LF007, 007DCDA

Double Check Valve Assemblies Double Check Detector Assemblies

Sizes 2" - 3"

Repair Kits

When ordering specify Ordering Code, Kit No., and Valve Size.

| | ORDERING Code | KIT NO. | SIZE | LIST PRICE |
|-------|------------------|------------------|------------|------------|
| | First Che | eck Kit | | |
| o.i., | 0887980 | RK 007DCDA CK1 | 2" | \$112.50 |
| | 0794006 | LFRK 007 CK1 | 2 1/2", 3" | 541.50 |
| | 0794007 | LFRK 007DCDA CK1 | 2 1/2", 3" | 562.00 |

Kit consists of: seat, seat 0-ring, disc assembly, spring, spring retainer, check cage and cover 0-ring.

Second Check Kit

| 1 RK 007DCDA CK2 | 2" | 101.50 |
|--------------------|----------------|---------------------------|
| 8 LFRK 007 CK2 | 2 1/2", 3" | 515.50 |
| 9 LFRK 007DCDA-CK2 | 2 1/2", 3" | 515.50 |
|) | 8 LFRK 007 CK2 | 8 LFRK 007 CK2 2 1/2", 3" |

Kit consists of: seat, seat 0-ring, disc assembly, spring, spring retainer, check cage and cover 0-ring.

Complete Rubber Parts

| o iu | 0887982 | RK 007DCDA RT | 2" | 30.25 |
|----------|---------|---------------|------------|--------|
| Z | 0887287 | RK 007 RT | 2 1/2", 3" | 118.50 |
| | 0887967 | RK 007DCDA RT | 2 1/2", 3" | 118.50 |
| | | | | |

Kit consists of: 2 seat discs, 2 seat 0-rings, and cover 0-ring.

| Cover Kit | | | |
|-----------|--------------|------------|--------|
| 0887983 | RK 007DCDA C | 2" | 133.50 |
| 0887288 | RK 007 C | 2 1/2", 3" | 367.00 |
| 0887970 | RK 007DCDA C | 2 1/2", 3" | 367.50 |
| | | | |


Kit consists of: cover, cover O-ring.


Seat Kit

| | 0887984 | RK 007DCDA S1 | 2" | 85.00 |
|---|---------|---------------|------------|-------|
| Ĥ | 0887985 | RK 007DCDA S2 | 2" | 85.00 |
| Œ | 0887289 | RK 007 S1 | 2 1/2", 3" | 91.25 |
| 9 | 0887290 | RK 007 S2 | 2 1/2", 3" | 91.25 |
| | 0887968 | RK 007DCDA S1 | 2 1/2", 3" | 91.25 |
| | 0887969 | RK 007DCDA S2 | 2 1/2", 3" | 91.25 |

Kit consists of: seat, seat O-ring and cover O-ring.

Check Assemblies





*The wetted surface of this product contacted by consumable water contains less than 0.25% of lead by weight.