Series 007, LF007, 007DCDA

Double Check Valve Assemblies Double Check Detector Assemblies

Sizes 2" - 3"

Repair Kits

When ordering specify Ordering Code, Kit No., and Valve Size.

| | ORDERING CODE | KIT NO. | SIZE | LIST PRICE |
|------|------------------|------------------|------------|------------|
| | First Check Kit | | | |
| o iu | 0887980 | RK 007DCDA CK1 | 2" | \$124.50 |
| A H | 0794006 | LFRK 007 CK1 | 2 1/2", 3" | 597.50 |
| - 11 | 0794007 | LFRK 007DCDA CK1 | 2 1/2", 3" | 620.50 |

Kit consists of: seat, seat 0-ring, disc assembly, spring, spring retainer, check cage and cover 0-ring.

Second Check Kit

| o iu | 0887981 | RK 007DCDA CK2 | 2" | 112.50 |
|------|---------|------------------|------------|--------|
| LEAL | 0794008 | LFRK 007 CK2 | 2 1/2", 3" | 569.00 |
| | 0794009 | LFRK 007DCDA-CK2 | 2 1/2", 3" | 569.00 |

Kit consists of: seat, seat 0-ring, disc assembly, spring, spring retainer, check cage and cover 0-ring.

Complete Rubber Parts

| ம் | 0887982 | RK 007DCDA RT | 2" | 33.75 |
|------------|--|---------------|------------|--------|
| 4 H | 0887287 | RK 007 RT | 2 1/2", 3" | 131.00 |
| -111 | 0887967 | RK 007DCDA RT | 2 1/2", 3" | 131.00 |
| | Kit consists of: 2 seat discs, 2 seat 0-rings, and cover 0-ring. | | | |

Cover Kit

0887983 RK 007DCDA C 2" 148.00

0887288 RK 007 C 2 1/2", 3" 405.00

0887970 RK 007DCDA C 2 1/2", 3" 405.50


Kit consists of: cover, cover 0-ring.


Seat Kit

| | 0887984 | RK 007DCDA S1 | 2" | 93.75 |
|---|---------|---------------|------------|--------|
| Н | 0887985 | RK 007DCDA S2 | 2" | 93.75 |
| Œ | 0887289 | RK 007 S1 | 2 1/2", 3" | 101.00 |
| 9 | 0887290 | RK 007 S2 | 2 1/2", 3" | 101.00 |
| | 0887968 | RK 007DCDA S1 | 2 1/2", 3" | 101.00 |
| | 0887969 | RK 007DCDA S2 | 2 1/2", 3" | 101.00 |
| | | | | |

Kit consists of: seat, seat 0-ring and cover 0-ring.

Check Assemblies





^{*}The wetted surface of this product contacted by consumable water contains less than 0.25% of lead by weight.