


A WATTS Brand

# LF860, LF866

### 2½" - 10" Reduced Pressure Zone Assemblies/Reduced Pressure Zone Detector Assemblies



	Ordering Code	Style	Size	List Price
	Disc Assembly			
iu	905466	ALL	2 1/2" & 3"	\$ 234.50
E	905467	ALL	4"	246.00
AD	905468	ALL	6"	323.00
3	905469	ALL	8" & 10"	599.50
	ICH In almala a Harris	11 10 00 00 0	4 05 00	

Kit Includes: Items 11, 12, 22, 23, 24, 25, 26

#### **Check Rubber Kit**

iu	905490	ALL	2 1/2" & 3"	134.00
H	905491	ALL	4"	146.00
Q.	905492	ALL	6"	168.00
ä	905493	ALL	8" & 10"	279.00

Kit Includes: Items 10, 25, 30, and 51 and Seat Ring O-Rings

#### **Spring Module**

įų.	905507	LF860, 866 (1st)	2 1/2" & 3"	224.00
Ë	905508	LF860, 866 (1st)	4"	246.00
EAD	905509	LF860, 866 (1st)	6"	301.00
2	905510	LF860, 866 (1st)	8" & 10"	334.00
iu	905470	LF860 (2nd)	2 1/2" & 3"	101.00
H	905471	LF860 (2nd)	4"	130.00
Q.	905472	LF860 (2nd)	6"	211.00
12	905473	LF860 (2nd)	8" & 10"	234.50
iu	905608	866 (2nd)	2 1/2" & 3"	144.00
E	905609	866 (2nd)	4"	166.00
EAD	905610	866 (2nd)	6"	248.50
ä	905611	866 (2nd)	8" & 10"	242.00

Kit Includes: Item 15

	Seat Ring / Ar	m Assembly		
iu	905486	ALL	2 1/2" & 3"	422.00
E	905487	ALL	4"	438.00
AD	905488	ALL	6"	625.00
4	905489	ALL	8" & 10"	622.00

Kit Includes: Items 2, 3, 4, 5, 6, 46, 47, 48, 52

	Ordering Code	Style	Size	List Price
	Check Replace	ement Kit		
jų.	905511	860, 866 (1st)	2 1/2" & 3"	\$ 848.00
Ë	905512	860, 866 (1st)	4"	1,071.00
EAD	905514	860, 866 (1st)	6"	1,774.00
1	905515	860, 866 (1st)	8" & 10"	2,636.00
iu	905478	860 (2nd)	2 1/2" & 3"	843.00
H	905479	860 (2nd)	4"	1,062.00
EAD	905480	860 (2nd)	6"	1,545.00
4	905481	860 (2nd)	8" & 10"	2,254.00
iu	905612	866 (2nd)	2 1/2" & 3"	899.50
AD FRE	905613	866 (2nd)	4"	1,087.00
	905614	866 (2nd)	6"	1,578.00
1	905615	866 (2nd)	8" & 10"	2,364.00

Kit Includes: Check Assembly, Seat Ring Arm, Spring Assembly, and Disc Assembly. Cover 0-Rings on all Check Kits

#### **Full Rubber Kit**

ľ	905535	ALL	2 1/2" & 3"	323.00
ŀ	905566	ALL	4"	334.00
Q	905579	ALL	6"	356.50
ŀ	905580	ALL	8" & 10"	467.00
	ICI I a al cala a	/E T ObI I DVA		

Kit Includes: (For Two Checks and RV)

#### **Cover Assembly**

iu	905376	ALL	2 1/2" & 3"	328.50
ᄩ	905377	ALL	4"	373.00
3	905378	ALL	6"	431.00

Kit Includes: Items 7, 10, 18, 19

<sup>\*</sup>The wetted surface of this product contacted by consumable water contains less than 0.25% of lead by weight.

Supersedes all other price lists / Prices subject to change / Weights are estimated

<sup>&</sup>lt;sup>1</sup>Grooved ends available on all OS&Y gate valves in some models and sizes. Expect larger lead times.


1,330.00



## LF860, LF880V, LF866, LF886V **Relief Valve Repair Kits**

	Ordering Code	List Price
	RV Rubber Kit	
LEAD FREE	905602	\$ 190.50
	Kit Includes: Items 2, 4, 10, 12, 17 & 29	
	RV Repair Parts Kit	
LEAD FREE	905603	368.00
	Kit Includes: Items 2, 4, 6, 7, 8, 9, 10, 11,	12, 17, 18, 19,
	28, 29, 31, 32, 33, 34 & 35	
	Complete RV W/Elbows	
	(LF860/LF866 2½"- 8")	
LEAD FREE	905606	1,164.00
	Kit Includes: Fully Assembled	
	Complete RV W/Elbows (LF880V, LF886V, LF860/LF866 10")	

905607 Kit Includes: Fully Assembled



## LF856, LF876V, LF866, LF886V

**Bypass Assemblies and Bypass Repair Kits** 

	Ordering Code	Size	List Price
	LF856/LF86	6	
벁	905629	2 1/2" - 4"	\$ 815.00
EAD	905630	6" - 10"	843.00
	LF876V/LF8	86V	
įщ	905625	2 1/2 - 3"	896.50
ij	905638	4"	910.50
l L	905626	6"	919.50
ê	905639	8"	929.00
Ë	905640	10"	939.00

Kit supplied loosely assembled

## LF856, LF876V, LF866, LF886V cont.

**Bypass Assemblies and Bypass Repair Kits** 

	Ordering Code	Size	List Price
	LF856/LF88	36/LF876V/LF886V/Bypass Hose	
ä	905631	2 1/2 - 4"	39.25
LEAD	905632	6 - 10"	58.50
	LFFRK 619	CK1 Bypass Check Repair Kit	
LEAD FREE	905633	2 1/2" - 10"	105.50
	LFFRK 619	Bypass Check Assembly	
FREE.	905634	2 1/2" - 10"	301.50

<sup>\*</sup>The wetted surface of this product contacted by consumable water contains less than 0.25% of lead by weight. Supersedes all other price lists / Prices subject to change / Weights are estimated